

Report Date: 12/2/2022

**Application No** TRE-APP-APP22-38801549

**Permit No** TRE-PMT-22-38901549

**Site Address** 

Type of Record Building/Permits/Tree Permit/Permit

**Date Issued** 12/02/2022

Record Status Active

Primary Applicant Alejandro Gomez

Scope of Work PLAT-22-11800386 - Heron Valley II Enclave

PLATTING, SITE WORK

**Approval Comments** 

Completeness Review Comments Completeness review

approved, required documents submitted. No tree removal permitted with this approved including in the right-of-way or easements. Technical review pending payment of invoiced tree permitting fees and passing the preliminary tree

inspection.



Report Date: 12/2/2022

Technical Review - Tree Land Development

Comments BSA Tree #

TRE-APP-APP22-388015449
// Plat #22-11800386 // Heron
Valley II // Streetscape
Required Not // A4 // ICL //
2015 // 12/2/2022 / CGJ

STATUS: APPROVAL FOR ONLY PLATTING AND TREE REMOVAL ANY TREE REMOVAL OUTSIDE OF THE APPROVED TREE PERMITTED UNIT SHALL SUBMIT A SEPARATE TREE APPLICATION FOR REVIEW AND APPROVAL PRIOR TO ANY START OF WORK

APPROVAL VALID FOR 180 DAYS

\*\*\*\*APPLICANT MUST DOWNLOAD THE APPROVED PLAN FROM THE BUILD SA TREE APPLICATION ATTACHMENTS/DOCUMENT S FOLDER.

STREETSCAPE BOND NOT REQUIRED

TREE SURVEY METHOD

TREE NOTE ON PLAT

PLANTING: Each lot shall receive 2 – 1.5" caliper inch native large Appendix E shade tree.

No tree species may be greater than 25% of the total

This subdivision is subject to a Master Tree Plan BSA TRE-APP-APP22-38801549 which requires compliance by



Report Date: 12/2/2022

the owners of all property withi the plat boundary, and their employees and contractors, and shall be binding on all successors in title except for owners of single-family residential lots subdivided hereunder for which construction of a residential structure has been completed. The Master Tree Plan is on file at the City of San Antonio Arborists Office. No Trees or Understory shall be removed without prior approval of the City Arborist Office per 35-477(h).

Prior to commencement of any activities requiring a tree permit, the applicant shall schedule a pre-construction meeting with the City Arborist to review procedures for protection and management of all significant, heritage or mitigation trees. A protective barrier, beginning at the outside of the dripline of the tree, to protect the root protection zone shall be erected and maintained until construction is completed. The barrier shall be in place before any site work is initiated and maintained throughout the construction process.

It shall be the responsibility of the permit holder to maintain a copy of the approved tree plans, tree permit and the conditions of approval readily available at the site at all times Notification and written approval from the city arborist of any changes to the approve tree preservation are required before commencement of any



Report Date: 12/2/2022

work that is the subject of the change or field adjustment

Contractor is responsible for providing a licensed Tree Maintenance Professional throughout the project. Staging, Parking, Storage, Employee Parking:

- 1) Staging, parking, storage areas and project limits must be discussed and approved with the inspector during the pre-construction/fencing inspection.
- 2) All offsite staging, storage, project trailers, employee parking, are required to obtain a Temporary Uses Certificate of Occupancy.
- 3) No equipment, vehicles or materials shall operate or be stored within the root protection zone.

All broken branches & exposed roots 2" in diameter or greater of Significant, Heritage or mitigation trees shall be cut cleanly. All Oak tree wounds must be painted within 30 min.

#### Root Protection Zone:

- 1) A root protection zone musbe established around the trun of each tree preserved or mitigation tree. The root protection zone shall be an area defined by an average radius extending outward from the trunk of the tree a distance of one (1) linear foot for each inch (DBH).
- 2) Avoid cutting roots larger than one (1) inch in diameter. Excavation beneath the dripling shall proceed with caution. Roots will be cut with a saw or by hand.



Report Date: 12/2/2022

3) The root protection zone area shall be preserved at natural grade, with natural groundcover.

4) No cutting, filling, trenching root disturbance, soil disturbance, or construction impacts shall occur closer to the trunk than one-half (½) the root protection.

## **Required Inspections**

Tree - Fencing
Tree - Fencing Follow Up

Tree - Pre-Construction Meeting

# **Inspection Status**

Status

Pending Pending

Pending

### **Related Records**

(This is other Permits Created from the Applications, Amendments etc)

Record Number Record Type

LAND-PLAT-22-11800386 Major Plat Under Review